

Caretaker Report 5-14-22

- There was an issue with the alarm system and Piper Fire Alarm responded. It may have been caused by lightning. Piper reset the alarm and will make plans to return.
- The small golf cart had a steering issue, Kappy's repaired it and it is back in service.
- Stoney repaired a screen issue at C-9 and patched a hole in the ceiling in their crib.
- The brush in the burn area was burned with the assistance of Chief Bill.
- Stoney and Tom started repairing the drywall on D-9 and K-7.
- The ceiling damage in E-12 was caused by a vent that has been sealed. The repairs will be scheduled around the owner's use of the unit.
- Tom installed a new stern light on the ferry.
- Tom graded the roads using the tractor.
- The new weather station has been installed on the Island Dock (named HBBC Dock 73). The older unit will be installed on the mainland.
- New Captain Dan will finish his training next week.
- Captain Slavek will be back on May 21, 2022, until he returns the schedule has been split between Captain Mike and Captain Tom.